

Test Report

01481000-White Goose Down 90/10

IDFL # 19-295079

Wed 11 Sept. 2019

Arrival Date: Report Date:


3-Day Fri 6 Sept. 2019 Wed 11 Sept. 2019

Germany

Plumage Sample Type: Shipped By: DHL 3379602461

Sample Identification: 01481000-White Goose Down 90/10 US-Standard, F/P 850cuin

S/C Weltop 35/2019 (Exped)



SN EN ISO/EC 17025:2005

¹ SAS Accredited

This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.

IDFL LABORATORY AND INSTITUTE

IDFL SALT LAKE 1455 South 1100 East Salt Lake City, UT 84105 +1 801 467 7611

info@idfl.com

IDFL EUROPE AG Zürcherstrasse 282 CH-8500 Frauenfeld Switzerland +41 52 765 1574 europe@idfl.com

IDFL CHINA Tonghui Mid-Road 688, Xiaoshan Hangzhou Zhejiang 311200 China +86 571 8273 6561 china@idfl.com

IDFL TAIPEI

taiwan@idfl.com

2F., No. 163 Sec. 2, Wenhua Rd. Banqiao District, New Taipei City Taiwan +886 2 2259 1178

Approved By www.idfl.com Client 95 Sample 3 of 7

Page 1 of 3





Test Report

01481000-White Goose Down 90/10

Wed 11 Sept. 2019

Test Orders Summary				
Test	Test Component	Result	Expected Value	
Content IDFB Part 3 2013	Down Clusters	90.6%	91	
Species Down & Feathers IDFB Part 12 2013	Total Goose	98%	-	
	Total Duck	2%	-	
Steam Fill Power IDFB Part 10-B 2015	Final Fill Power Volume	850 in ³ /30g	860	

SN EN ISO/EC 17025:2005

¹ SAS Accredited

info@idfl.com

This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.

IDFL LABORATORY AND INSTITUTE

IDFL SALT LAKE 1455 South 1100 East Salt Lake City, UT 84105 USA +1 801 467 7611 DFL EUROPE AG
Zürcherstrasse 282
CH-8500 Frauenfeld
Switzerland
+41 52 765 1574
europe@idfl.com

IDFL CHINA
Tonghui Mid-Road 688, Xiaoshan
Hangzhou Zhejiang 311200
China
+86 571 8273 6561
china@idfl.com

IDFL TAIPEI
2F., No. 163 Sec. 2, Wenhua Rd.
Banqiao District, New Taipei City
Taiwan
+886 2 2259 1178
taiwan@idfl.com

Approved By www.idfl.com Client 95 CH Sample 3 of 7

Page 2 of 3





Test Report

01481000-White Goose Down 90/10

Wed 11 Sept. 2019

Content IDFE	B Part 3 2013 ¹
Down Clusters	90.6%
Down Fibers	3.6%
Waterfowl Feather Fibers	0.9%
Waterfowl Feathers	4.5%
Broken and Damaged Waterfowl Feathers	0.2%
Quill	0.0%
Landfowl	0.0%
Residue	0.2%
Total	100.0%

Species Down & Feath	thers IDFB Part 12 2013 ¹
Goose Down	98%
Duck Down	2%
Goose Feathers	100%
Duck Feathers	0%
Total Goose	98%
Total Duck	2%

	Steam Fill Power IDFB Part 10-B 2015 ¹
	Volume 850 in³/30g
ľ	

SN EN ISO/EC 17025:2005

¹ SAS Accredited

This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.

china@idfl.com

IDFL LABORATORY AND INSTITUTE

IDFL SALT LAKE 1455 South 1100 East Salt Lake City, UT 84105 USA +1 801 467 7611

info@idfl.com

DFL EUROPE AG
Zürcherstrasse 282
CH-8500 Frauenfeld
Switzerland
+41 52 765 1574
europe@idfl.com

IDFL CHINA
Tonghui Mid-Road 688, Xiaoshan
Hangzhou Zhejiang 311200
China
+86 571 8273 6561

IDFL TAIPEI

2F., No. 163 Sec. 2, Wenhua Rd. Banqiao District, New Taipei City Taiwan +886 2 2259 1178 taiwan@idfl.com Approved By www.idfl.com Client 95 CH Sample 3 of 7

Page 3 of 3